
## **CHAPTER 5**


Suggested Drafting Techniques-Metric

# SUGGESTED TEXT PLACEMENT AND DRAFTING TECHNIQUES


### DIMENSIONS ARE BASED ON 1:500 RATIO DRAWINGS



I. LS=SPACING BETWEEN LINES OF TEXT




### II. TEXT ABOVE LINE




SECTION A-A

## III. VARIOUS WAYS OF SHOWING DIMENSION LINES




NOTE: AS MUCH AS POSSIBLE "LEADER ARROWS" SHALL BE PLACED PARALLEL TO EACH OTHER.




NOTE: BREAK LEADER ARROW PASSING THRU TEXT AND DIMENSION LINES. NO BREAKS WHEN IT PASSES THRU AN OBJECT.

TYPICAL LINE BREAKS WHEN WITNESS LINES DIMENSION LINES, AND LEADER ARROW CROSSES ONE ANOTHER. DON'T BREAK LEADER ARROW WHEN IT PASSES THRU ELEMENTS OR OBJECTS.




### TEXT PLACEMENT WITH OBJECTS

NOTE: DO NOT PLACE TEXT ON ELEMENTS OR OBJECTS



### TEXT WITH MAJOR INTERSECTION OR STREETS



### TEXT WITH SIDE STREETS AND ENTRANCES

